


| ADVANCED SEARCH | PRODUCTS | WARRANTIES | SHOPPING CART | HOME | ▲

FIG. 1



⊗Wa	rrant	i	~ 2	4	***						
WELCOME ROBERT THOMSON UPDATE PERSONAL INFORMATION											
ADD NEW LOCATION 22a CHANGE USER						)	,				
SORT/DELETE	LOCATION									<u>C</u> ,	42
HOME	38	34	<u>E</u>	<u>)II</u> 68			62		64	36	-
MANUFACTURER		MODEL		72	<i>30</i> )	RODUC	CT ( 63 )	66		SERIAL NUMBER	
SONY	TV	21	HELF			REFER		TRADE	DISPOSE	21-1234	
SONY	TV	27	HELF			REFER					
SONY	TV	<u>27</u>	HELF					TRADE	DISPOSE	27-2345	ļ
SONY	VCR	32 HIFI	HELP				INSURE	TRADE	DISPOSE	32-1222	
SONY	TUNER	T101	HELP				INSURE INSURE	TRADE TRADE	DISPOSE DISPOSE	VC-1111 T-12345	H
IBM _	LAPTOP	770E	HELP			REFER		TRADE	DISPOSE	T-12346	H
TOTAL	3	7,00	11,55	7100E330TIES	7	INCI LIX	MOUNE	INNUL	DIST USE	1-12340	H
CAR 44 EDIT 46											
MANUFACTURER	PRODUCT	MODEL		PRODUCT				SERIAL NUMBER			
SONY	RADIO/CD	RCD	HELP	ACCESSORIES	REPAIR	REFER	INSURE	TRADE	DISPOSE		H
TOTAL											П
HOLIDAY H	OME		ED	<u>iT</u>	- I	• • • • • • • • • • • • • • • • • • •		<u> </u>		L	
MANUFACTURER	PRODUCT	MODEL	PRODUCT				SERIAL NUMBER				
HITACHI	TV	60	HELP	<b>ACCESSORIES</b>	REPAIR	REFER	INSURE	TRADE	<u>DISPOSE</u>	H-1234	
TOTAL											7
NATALIE AT	COLLEG	Ε	ED	<u>IT</u>			•	•	•		$\int$
MANUFACTURER <u>32</u>	PRODUCT	MODEL	PRODUCT					SERIAL NUMBER			
<u>IBM</u>	LAPTOP	<u>760</u>	HELP	<b>ACCESSORIES</b>	REPAIR	REFER	INSURE	TRADE	DISPOSE	982-1234	
TOTAL											
IAN AT SCHOOL EDIT											
MANUFACTURER 32	PRODUCT	MODEL	PRODUCT				SERIAL NUMBER	1			
COMPAQ	LAPTOP	<u>1643</u>	HELP	<u>ACCESSORIES</u>	REPAIR	REFER	<u>insure</u>	TRADE	<u>DISPOSE</u>	CQ-1234	
TOTAL											7

FIG. 3A




FIG. 3B

COMPANY FIRST NAME LAST NAME ADDRESS CITY	
UPDATE	RESET

FIG.4

- 54

WHERE WOULD YOU LIKE TO GO? **∮** Warranti

②HELP 個 HOME

CUSTOMERS Repair Status

PROBLEM DETAILS

2/21/00 A REPORTED 2 STATUS 4 PROBLEM TYPE 1

COMPANY

NAME

**PRODUCT** 

HARDWARE
XL CAPITAL LTD
PAUL BENEVIDES
DCR-TR7000
DIGITAL CAMCORDER
SONY CORPORATION OF AMERICA DESCRIPTION

MANUFACTURER

THIS COULD BE FURTHER DETAIL PROBLEM

~ 52

OFF—SITE REPAIR SERVICE ORDER GENERATED FOR MR FIXIT FOR UPS EXPRESS 2/21/00 12:20:00 | PRODUCT DELIVERED 02/21/2000 TO FRED 48 SHIPPING REQUEST GENERATED (LEG 1) 2/21/00 12:19:00 | PRODUCT COLLECTED 02/20/2000 区 ACTIVITY LOG -PROBLEM ENTERED 2/21/00 12:12:00 2/21/00 12:17:00 activity date

FIG.5

С	OMPANY					
	NAME					
DATE						
PRODUCT \$58						
MANUFACTURER FAULT TYPE						
PROBLEM	60					
SUBMIT	RESET					

FIG.6




FIG.7





FIG.8

694		_				_
	COST	100	80	75	30 20	30
(92	FAULT	NO PICTURE	OWY PICTU	ON SOUND	OTHER	NO ALARM
C <sup>38</sup>	DESC.	VCR	VCR	VCR	VCR	VCR
	CODE	A-100	A-100	A-100	A-100	A-100
(32	MFG )	XXX	XXXX	XXXX	XXX	XXX

FIG.9







FIG. 11









FIG. 13











FIG. 17



POINT OF SALE REGISTRATION

- INFORMATION

FIG. 18




FIG. 19

CASH CARD REGISTRATION

----- CASH CARD